

KIRA TECH TIP

Jog To G30 Position

Orient the spindle first with an M19.
Manually jog up to the G30 Position

This technical bulletin is provided as a free service by Shoprag.com