

# KIRA TECH TIP

## Cannot Program XO YO in MDI Mode

This is because all MDI moves are in incremental

Change Parameter:

#3104 b4      MAB=0

MDI moves will be performed by G90 or G91