

# KIRA TECH TIP

## Change Machine Position Display Between Inch and Metric

Change Parameter:  
#310460      MCN=0

This technical bulletin is provided as a free service by Shoprag.com